



East India Quay

Tail O' The Bank (PH)

VIRGINIA STREET

Victoria Quay  
 Historic Maintenance Depth in  
 Victoria Harbour 3.9m CD

RUE END STREET

7 to 8 9

Posts

Call Centre

EI Sub Sta  
 Mast

EI Sub Sta

Hotel

MAIN STREET

3.8m

amb Sta

MLWS  
 FB  
 MS  
 Scotts Drydock Built 1810

2F.G(vert)